



Drainage Ravin

Miller Coulee Drain • Hixon Forest Nature Center
La Crosse, Wisconsin



Drainage Ravin



Synergy With Nature™

Drainage Ravin

Application: Protection for exposed natural gas line

Owner: Northern Natural Gas

General Contractor: Submar

Location: Hixon Forest Nature Center, La Crosse, Wisconsin

Square Feet: 67,890

Submar completed it's initial Hixon Forest Nature Center site survey for Northern Natural Gas in May of 2009. Substantial erosion from rainfall was causing exposure of a natural gas pipeline running through the center. Repair and mitigation procedures would have been an every-day job if the location had not been a nature center. Special care was taken not to damage sensitive vegetation nor disturb the native wildlife and an environmental inspector was on-site at all times checking all erosion control BMPs because of the rainy weather. Access was a major issue due to heavy use by joggers and walkers of trails in the Hixon Forest. These trails had to be kept in good condition while being used by the necessary heavy equipment needed to perform the job. Submar completed the job using native seeds to restore the right-of-way with vegetation, solidified the trail and the ravine banks in the immediate area, installed pipeline protection and kept on schedule.



805 Dunn Street
Houma, Louisiana 70360
985.868.0001
FAX 985.851.0108
EMAIL: submar@submar.com
www.submar.com